

## Web update of DDS-CAD Architect & Construction 6.5 – December 2009

Update has been executed with priority on wall edit

### News in DDS-CAD Architect

- **Move wall**

Problems have been reported in connection with moving wall and object having been inserted into the wall. Profound testing of this has now been executed, with hopefully a better result concerning complications arising in connection with variants of combinations

- **Dimension longitudinal**


A problem has been reported when pointing in the correct wall sections for dimensioning along the wall. This proved to be related to split walls – and has now been fixed.

- **Section with symbols**


The section is right regarding to show symbols (window/door/opening) when a distance from section line to the symbols are specified.

- **Module net**

Inserting a module net can be executed via a Java Script. You will find this in the main menu – sub menu Format.



An option has been included for selecting colour for the individual panels in the module net





## News in DDS-CAD Construction version 6.5 – December 2009

### • Changed font setup in Construction

In connection with starting to use Truetype fonts in Construction, we would like to ask customers using individual font numbers on, for instance, user defined sheets, lists and title fields in Constuction, to update these fonts. Those using default setup will not have to take any actions.

Look for files with the name:

**BCP-SH?.BIN**

**BCP\_TI?.BIN**

**FI99??.BIN**

or adapted libraries (FI0?????.LIB) containing files where individual font numbers are used..

If you should have such files in your user folder, you should check the command TD in the file and may be change it. TD's 4 argument should be set to a "monospaced" font. DDS recommends type -81 (Lucida Console), or you can make connection with a corresponding "monospaced" truetype font.

In the program the font no. 81 is already set to "Monospaced" font (Lucida Console), and font no. 82 to proportional font (MS Reference Sans Serif).

Contact DDS if you have questions, or if you need help with this.

### Updates

\* The program will now give a message if you try to draw joists outside the active area.

\* When inserting parallel joist, width adjustment will now only be made on the indicated side.

---

### • Automatic wall treatment

In automatic wall treatment, in the dialogue box "View Simplified Plan", is a choice added for how to view the panel numbers/names in the plan.

